

USE OF ACRYLIC DIFFUSERS WITH METAL HALIDE FIXTURES

ENGINEERING TECHNICAL LETTER

DR. DARYL I. HAMMOND
HQ AFCESA/CESM, TYNDALL AFB, FL

Approved for public release; distribution is unlimited.



AIR FORCE CIVIL ENGINEER SUPPORT AGENCY
139 BARNES DR, SUITE 1
TYNDALL AIR FORCE BASE, FLORIDA 32403-5319

Report Documentation Page			Form Approved OMB No. 0704-0188	
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>				
1. REPORT DATE 05 FEB 2005	2. REPORT TYPE	3. DATES COVERED		
4. TITLE AND SUBTITLE Use of Acrylic Diffusers With Metal Halide Fixtures		5a. CONTRACT NUMBER		
		5b. GRANT NUMBER		
		5c. PROGRAM ELEMENT NUMBER		
6. AUTHOR(S) Daryl Hammond		5d. PROJECT NUMBER		
		5e. TASK NUMBER		
		5f. WORK UNIT NUMBER		
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) HQ Air Force Civil Engineer Support Agency, 139 Barnes Dr., Suite 1, Tyndall AFB, FL, 32403-5319		8. PERFORMING ORGANIZATION REPORT NUMBER AFCESA-TR-2006-0017		
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)		10. SPONSOR/MONITOR'S ACRONYM(S)		
		11. SPONSOR/MONITOR'S REPORT NUMBER(S)		
12. DISTRIBUTION/AVAILABILITY STATEMENT Approved for public release; distribution unlimited.				
13. SUPPLEMENTARY NOTES				
14. ABSTRACT This ETL provides recommendations for use of acrylic diffusers with metal halide lamps and fixtures at Air Force installations to minimize the possibility of personal injury, burns, and fire from lamp ruptures.				
15. SUBJECT TERMS				
16. SECURITY CLASSIFICATION OF:			17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES 7
a. REPORT unclassified	b. ABSTRACT unclassified	c. THIS PAGE unclassified		

Notice and Signature Page

Using Government drawings, specifications, or other data included in this document for any purpose other than Government procurement does not in any way obligate the U.S. Government. The fact that the Government formulated or supplied the drawings, specifications, or other data does not license the holder or any other person or corporation; or convey any rights or permission to manufacture, use, or sell any patented invention that may relate to them.

This report was cleared for public release by the Air Force Civil Engineer Support Agency, Tyndall AFB, FL, Public Affairs Office and is available to the general public, including foreign nationals. Copies may be obtained from the Defense Technical Information Center (DTIC) (<http://www.dtic.mil>).

AFCESA-TR-2006-0017 HAS BEEN REVIEWED AND IS APPROVED FOR PUBLICATION IN ACCORDANCE WITH ASSIGNED DISTRIBUTION STATEMENT.

FOR THE DIRECTOR:

//SIGNED//

Dr. Daryl I. Hammond, P.E.
Acting Chief of Mechanical Division

//SIGNED//

Brent E. Hill, Colonel, USAF
Director of Engineering Support

This report is published in the interest of scientific and technical information exchange and its publication does not constitute the Government's approval or disapproval of its ideas or findings.



DEPARTMENT OF THE AIR FORCE
HEADQUARTERS AIR FORCE CIVIL ENGINEER SUPPORT AGENCY

5 FEB 2005

FROM: HQ AFCESA/CESM
139 Barnes Drive Suite 1
Tyndall AFB FL 32403-5319

SUBJECT: **Engineering Technical Letter (ETL) 05-1: Use of Acrylic Diffusers with Metal Halide Fixtures**

1. Purpose. This ETL provides recommendations for use of acrylic diffusers with metal halide lamps and fixtures at Air Force installations to minimize the possibility of personal injury, burns, and fire from lamp ruptures.

2. Application. Requirements in this ETL are mandatory.

2.1. Authority:

- Air Force Instruction (AFI) 32-1064, *Electrical Safe Practices*
- Unified Facilities Criteria (UFC) 3-520-01, *Interior Electrical Systems*

2.2. Effective Date: Immediately.

2.3. Intended Users:

- Major command (MAJCOM) engineers
- Base civil engineers (BCE)
- Base maintenance organizations

2.4. Coordination: MAJCOM electrical engineers
Air Force Safety Center

3. Referenced Publications.

3.1. Air Force:

- Air Force Regulation (AFR) 91-12, *Electrical Safe Practices*, available at http://www.afcesa.af.mil/ces/cesm/cesm_electrical.asp
- AFI 32-1064, *Electrical Safe Practices*, available at <http://www.e-publishing.af.mil>

3.2. Joint Service:

- UFC 3-560-02, *Electrical Safety* (Draft), available at http://www.afcesa.af.mil/ces/cesm/cesm_electrical.asp
- UFC 3-520-01, *Interior Electrical Systems*, available at http://65.204.17.188//report/doc_ufc.html

4. Background.

4.4.1. Metal halide lamps are designed to operate under high temperatures and pressure and are subject to unexpected rupture. When the arc-tube ruptures, the outer bulb may break and result in scattering pieces of extremely hot glass that, if not contained, may cause personal injury, burns, and fire.

4.4.2. Diffusers made of acrylic material, and without any other overlay or containment barrier, cannot adequately contain the molten glass when multiple catastrophic lamp ruptures occur. Consequently, molten glass, plastic, and metallic particles can drip or fall on personnel or equipment located under the lamp when the diffuser has been weakened by a previous lamp failure. Underwriters Laboratory (UL) listing requires the fixture's diffuser/lens to contain one lamp rupture.

5. Specific Requirements.

5.1. For existing projects in design and not yet awarded, and for new or planned projects, metal halide luminaries incorporating acrylic lens diffusers shall be UL listed and:

5.1.1. Contain a tempered glass overlay between the lamp and acrylic diffuser; or

5.1.2. Incorporate metal halide lamps rated for use in open luminaires (internal lamp shielding, typically termed "O-rated") if acrylic lens diffusers are used without a glass overlay. All lamp manufacturers' instructions and warnings shall be followed.

5.1.3. Follow guidance contained in paragraphs 5.3 through 5.6.

5.2. Metal halide luminaries that do not incorporate requirements of paragraph 5.1 and subparagraphs shall:

5.2.1. Have the diffuser/lens inspected for damage, cracking, or scarring from previous lamp ruptures. All damaged, cracked, or scarred units shall be replaced.

5.2.2. Comply with paragraph 5.1 and subparagraphs, if practical, by installing open rated lamps or retrofitting existing diffusers with tempered glass overlays. Otherwise, replace diffusers following any lamp rupture regardless if the acrylic diffuser appears damaged.

5.2.3. Replace any acrylic diffuser, tempered glass overlays, and high intensity discharge lamps with the exact specifications in the design and ensure UL requirements are met and maintained.

5.2.4. Follow guidance contained in paragraphs 5.3 through 5.6.

5.3. Relamp fixtures at or before the end of a fixture's rated life. Allowing lamps to operate until they fail is not advisable and may increase the possibility of arc tube rupture.

5.4. Turn off lamps at least once a week for a minimum of fifteen (15) minutes when they are in continuous operation.

5.5. Do not operate a fixture with missing, damaged, scarred, or broken diffusers/lens.

5.6. Do not touch the lamp with bare hands.

6. Point of Contact. Recommendations for improvements to this ETL are encouraged and should be furnished to Dr. Daryl Hammond, HQ AFCESA/CESM, 139 Barnes Drive, Suite 1, Tyndall AFB FL 32408-5319, DSN 523-6352, commercial (850) 283-6352, FAX DSN 523-6219, Internet Daryl.Hammond@tyndall.af.mil.

JOSUELITO WORRELL, Colonel, USAF
Director of Engineering Support

Atch
1. Distribution List

DISTRIBUTION LIST

DEPARTMENT OF DEFENSE

Defense Commissary Agency	(1)	AAFES	(1)
Design and Construction Division		ATTN: RE-C	
2250 Foulois St., Suite 2		PO Box 660202	
Lackland AFB, TX 78236		Dallas, TX 75266-0202	

SPECIAL INTEREST ORGANIZATIONS

Information Handling Services	(1)	Construction Criteria Base	(1)
15 Inverness Way East		National Institute of Bldg Sciences	
Englewood, CO 80150		Washington, DC 20005	